




Dr Toby Roberts FRENG FEng FGeol



Conwy Crossing North Wales, UK

East cut and cover

M10 blow

West cut and cover


Submerged tube tunnel

Main contractor: Costain Tarmac JV

Casting basin: Tunnel units cast in dry, basin flooded and units floated out to form tunnel



Typical section through perimeter bund





Conwy: Glacial Lake Deposits

Laminated clay, silt and sand


Artesian relative to excavation level








Section through bund showing dewatering scheme










Conwy M10 blow














Service duct: Constructed previously








Section through service duct





Section through service duct

Backfill locally +













Ground loss due to migration of fines: local piping of uncemented sand horizon in sandstone

Mitigation: Effective filter screens (discharge quality) + deeper cut-off?









Dr Toby Roberts FRENG FEng FGeol